


MeasumaX^{MX}

ELECTRONIC MICROMETER IP 65

10-1255, 10-1256

5. Power

Battery is a SR44, 1.5V. Replace the battery when the display is blurring or "  " appears.



If not used for 5 minutes, the power will auto-off. The micrometer can be switch on by pressing the "ON/OFF" key or by turning the spindle.

Power off the micrometer by pressing "ON/OFF" key to save the battery if not in use.

6. Data output

Data output interface is RS232C. The micrometer can be connected to PC's serial port by SPC cable. (Order No.40-400).

Series port format:

| Baud rate | Start bit | Data bit | Stop bit | Parity | Data logic |
|-----------|-----------|----------|----------|--------|------------|
| 1200 | 1 | 7 | 2 | none | reverse |

Data format:

| Order | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|---|----|----|---|---|---|---|---|----|----|
| Metric | S | N1 | N1 | N | . | N | N | N | CR | LX |
| Inch | S | N | . | N | N | N | N | N | CR | LX |

S: Minus or space

N1: Minus or space or digit 0-9

N: Digit 0-9

7. Specifications

Measuring force : 5~10N

Power consumption : <=35μA


Operating temperature : 0 ~ 40□

Storage temperature : -20 ~ 60□

IP65 (Resist water spray)

8. Precautions

Do not subject the gauge to blows or knocks• Do not drop the gauge or apply excessive force to the gauge• Do not disassemble the gauge• Do not press the key with a pointed object• Do not use or store the gauge under direct sunlight, or in an excessively hot or cold environment• Do not subject the gauge in strong magnetic fields and high voltage environment• Use a soft cloth or cotton rag when cleaning the gauge. Do not use any organic solvent such as acetone etc.• The spindle is designed so that it cannot be removed from the inner sleeve. Do not move it past the upper limit of the measuring range• Remove the battery if the gauge not in use for a long time



9. Trouble shooting

| Failure | Causes | Repairing |
|--|--|---|
| Display "E 1" Display "Exxxxx" | Measuring value over display range. | Reset the origin or convert to relative measuring mode. |
| Display "E 2" | The origin is too great. | Reset the origin. |
| Display "E 3" Display "E 8" | 1. The micrometer is disturbed. 2. Something wrong with sensor. | 1. Reset the battery. 2. Return the micrometer for repair. |
| Measuring value is not correct | 1. Measuring surfaces are dirty. 2. The origin isn't correct. | 1. Clean measuring surfaces. 2. Reset the origin. |
| Display is confusing or dead | Suffer to strong disturb. | Reset battery. |
| No display Display is blurring " " appears | Battery voltage under 1.45V. | Replace battery. |
| The output data is wrong | Battery voltage under 1.45V. | Replace battery. |